

## Under Review Notification

**Raised By:** VANESSA MOREL

**Product #:** DART TOOLING BELL

**Date:** 17.12.05

**Product Name:** M/TRANS CHIP DETECTOR DRAIN TOOL

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RB910-0002-1	RB910-0002 REV 5	Y	Y	N	N	Y	Y	Y	17-780	SEE ENGINEERING BEFORE MACHINING
RB910-0002-9	RB910-0002 REV 5	Y	Y	N	N	Y	Y	Y	17-780	SEE ENGINEERING BEFORE MACHINING
RB910-0002	RB910-0002 REV 5	Y	Y	N	N	Y	Y	Y	17-780	SEE ENGINEERING BEFORE MACHINING
RB910-0002-3	RB910-0002 REV 5	Y	Y	N	N	N	Y	Y	17-780	WRONG O-RING

**Description of Issue:** FIT ISSUE

RB910-0002-1: PRESS FIT WITH -9 WRONG  
 RB910-0002-9: PRESS FIT WITH -1 WRONG  
 RB910-0002-3: 2-013 WRONG O-RING, CHANGED TO McMaster#9464K16

**Distribution:**

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------